



NTH Consultants, Ltd.

Infrastructure Engineering
and Environmental Services



PRESENTATION:

Rehabilitation of Raw Water Conduit and Pedestrian Tunnel

PRESENTED BY:

John R. Kosnak, P.E.



**INTERNATIONAL CONCRETE REPAIR INSTITUTE
2014 Spring Convention - Infrastructure Repair**

Follow Us:
NTH Consultants




March 19, 2014

Presentation Outline



- Introduction
- Background
- Investigation
- Findings / Evaluations
- Repairs
- Challenges
- Questions

PROJECT AREA: East and West Raw Water Conduits and Tunnel





Project Background (from Owner's Report)




- Visible cracks in walls and ceiling in Chemical Building
- Water leakage through cracks
- Other areas not visible without dewatering system

Raw Water Conduits




- Constructed in mid 1950s
- Dual Raw Water Conduits
 - 7 feet diameter
 - 7 feet square under Chemical Building
- Design Components
 - Cast-in-place Concrete
 - Reinforced Concrete Pipe
 - Steel-Plate Pipe
- Chlorination chamber
- Venturi Meters


Details of As-Designed Conduits



SECTION "A"



SECTION "B"



SECTION "C"



Site Access

- Permit required confined space
- Only 2 access points
 - Chemical Building
 - Low Lift Building
- Hazards
 - Chlorine
 - 36-inch bypass line
 - Venturi



NORTH EAST PLANT

NORTH EAST PLANT

CITY OF
WATER AND SEWER

01/12/2012

- **Only 1 conduit out of service at a time**
- **Repairs during low demand (winter months)**
- **Uninterrupted Plant Operation**
- **NSF 61 – Drinking Water Standard**

INVESTIGATION



Investigation



Panoramo Camera Inspection

- 360⁰ Digital recording
- pan / tilt and zoom by reviewer
- Measurement of features

Investigation

- Manned Entry
- Physical Measurements
- Concrete Cores
- Condition Assessment
- Sounding of Concrete



Investigation



Geophysical Survey

- Identify potential voids
- Comparison with historical soil information

FINDINGS / EVALUATIONS



Soundings

- No Delamination Observed

Concrete Cores


- Compressive Strength 7300 psi
- Tensile strength of Steel 60 ksi





Condition Assessment

- Fairly Good Condition
- Offset joints at Low Lift Bldg.
- Defects mainly in Chemical Bldg.
- Grout missing at some joints
- Visible Cracks and Fractures



Condition Assessment

- 1 Gushing & 1 Running leak
- Dripping & weeping leaks
- Previously sealed fractures were reopened and leaking
- Rubber seals sound but distressed – bars placed to hold in place

Petrographic Analysis



- W/C ratio – 0.33 to 0.35 for CIP, 0.35 to 0.37 for steel plate pipe
- No air entrainment
- Water –soluble chloride 0.03 to 0.04 % (well within ACI range)
- Cement paste friable, soft and degraded at surface
- Carbonation to 5/16-inch at surface

Carbonation Process



CO₂ in air or water

Ca(OH)₂ converts to CaCO₃
Other cement compounds decomposed

Hardened concrete

- * CaCO₃ dissolves in cold water – softens surface
- ** on dry surface CaCO₃ hardens and shrinkage may result

Structural Evaluation



- Conduits Structurally sound
- Cracking due to thermal movement
- Continued infiltration will impact durability

Sinkhole Evaluation




- Sinkhole developed near Low Lift Bldg. after returning East Conduit to service
- Owner re-drained East Conduit, replaced plug on drain line
- Owner filled sinkhole at surface
- NTH revisited site, performed supplemental GPR survey

Ground Penetrating Radar




- Several anomalies detected
- Sloping reflectors and soil pocket
- No indication of voids
- Anomalies match construction features shown on plans

Line 1




GPR Line Adjacent to Sinkhole,
Lines Indicate Limits of Observed Sinkhole
Effects

Line 2




GPR Line Above Sinkhole (Surface Feature),
Arrow Indicates Small Depression
Observed at Ground Surface

Line 3



GPR Line Adjacent to Sinkhole,
Anomaly Barely Discernable

Raw Water Conduit at Low Lift Building – area of sinkhole



Pedestrian Tunnel



Distress discovered while looking at exterior of East Conduit



- Fractures in wall
- Bowing of concrete
- Delamination in floor near Chemical Bld.
- Leak in Wall at Chemical Bld.

REPAIRS



Surface Preparation is KEY





Surface Preparation

1. Seal Leaks
2. Repair joints
3. Remove softened / carbonated layer
4. Repair fractures and cracks
 - Rout and seal with urethane
 - Inject with epoxy
5. Coat interior with Crystalline Waterproofing
6. Replace rubber seals



7. Repeat for opposite Conduit

8. Repair Pedestrian Tunnel

- Install new wall section
- Grout fractures/cracks
- Repair spalls/delaminations

CHALLENGES



Working in cold weather



Limited Site Access



Reinforcement on inside of Pedestrian Tunnel without effecting conduits




Working around conduits



Original rubber not available



Cold water under pressure (35°F)



Interpretation from Owner's Representative





John R. Kosnak, P.E.
Principal Engineer
jkosnak@nthconsultants.com
248-237-3907

QUESTIONS?

