

Restoration and Monitoring of a Thin Lightweight Reinforced Concrete Parking Slab

Pawan R. Gupta




Restoration



WALKER
RESTORATION CONSULTANTS

Project - Pegasus Apartments



Outline

- ❑ History/Challenges on the Project
- ❑ Repair Options Considered
- ❑ Mockup/Testing (Phase I)
 - Long Term Monitoring Results
- ❑ Repair Implementation (Phase II)
- ❑ Conclusions



Headquarters for General Petroleum Constructed in 1949

General Petroleum Bldg.,
Los Angeles, Calif.

Architect—Welton Becket,
A.I.A., and Associates

Contractor—
P. J. Walker Company

Builder's Hardware, Distributor—
Montgomery Hardware Co.



This fine building is equipped throughout
with McKinney Hinges



“MCKINNEY HINGES?

to be sure—you couldn't
make a better choice”



History of the Project

- ❑ Originally Constructed in 1949
- ❑ Major Renovation/Seismic Upgrade 2002
 - Level 2 and 3 Converted to Parking
 - Levels 3-13 converted to apartments
- ❑ Condition Assessment October 2011
 - Full depth concrete floor slab replacement
 - Level 2 – 1,450 sf Cost ≈ \$250,000
 - Level 3 – 14,500 sf Cost ≈ \$2,500,000

Added to Historical Buildings Register in 2004



Typical Slab Cracking



Full Depth Repair Locations



Full Depth Spall

03/07/2013



Full Depth Spall

03/07/2013



Punch Thrus

05/03/2012



Utility Access Ports


05/03/2012

Structural Floor System

- ❑ Light weight concrete 95pcf used in floor slab
- ❑ 3" thick slab
- ❑ Joist/beam spans 20'-2"
- ❑ Joist/beam spacing 3'-6"
- ❑ Top of joist/beams 2½" below finished floor
(beam/joist embedded in concrete by ½")
- ❑ Joists have a clip angle and rebar in the concrete slab
- ❑ Rebars: $F_y=40$ ksi /WWF mesh



Typical 3rd Floor Slab



Concrete Properties

GENERAL NOTES

- 1- All footings shall rest on firm, undisturbed natural soil at the elevations indicated. Character of soil sand and gravel with some clay.
- 2- Soil pressure based on the recommendation of the Foundation Engineers report subject to the approval of the Los Angeles City Bldg. Dept.
- 3- All concrete below First Floor Framing shall be Grade B and have a minimum compressive strength of 3000#/sq.in. at 28 days with a water cement ratio of 6 gals./sack of cement.
- 4- All other concrete shall be Grade A with light weight aggregate and have a minimum compressive strength of 2500#/sq.in. at 28 days with a water cement ratio of 6¾ gals./sack of cement. Light weight concrete shall weigh not more than 95#/cu.ft.
- 5- Gunite shall be mixed in proportions of 1 sack of cement to not more than 4½ cu. ft. of light weight aggregate and not more than 3 gals. of water per sack of cement at the discharge of nozzle. Gunite shall have a minimum compressive strength of 3000#/sq.in. at 28 days and weighing not more than 110#/cu.ft.
- 6- Reinforcing steel shall be new billet, deformed, intermediate grade conforming to A.S.T.M. designation No. A15-39. Reinforcing bars shall lap 40 diameters at splices and dowels, unless otherwise detailed.
- 7- Cement shall be a standard grade of Portland Cement conforming to A.S.T.M. designation C150-41.

$$f'_c = 2,500 \text{ psi}$$


$$w/c = 0.6$$

$$w = 95 \text{ pcf}$$


Very Light
Weight Concrete



Loading Conditions




As Designed




As Loaded

As Loaded



Wheel between Joists



Wheel at Joist

Slab Cracking Caused by Wheel Loads



Repair Options Considered

Demolish/Replace Slab

➤ Demolish Slab

- Saw-cut and Remove Slab
- Hydro Demolition


➤ Replace Slab

- Form New Concrete Slab
- Use Stay in Place Metal Forms (Deck)

Repair/Strengthen Existing Slab



Demolition Alternatives - Saw Cutting




Demolition Alternatives – Hydro-demolition



3rd Floor Plan

**Area of Slab Replacement
14,500 sq. ft.**




Challenges/Limitations

- Building is occupied
 - Noise/dust abatement
 - Minimum disruption to businesses
 - Preserve finishes in entrance lobby and restaurant
 - Work hours
- Lead Paint
- Small equipment access only
- Debris Removal (Congested Downtown Area!)
- Historic Building




Extent of Slab Replacement/Rehab

2nd Floor



First Floor Architectural



GENERAL NOTES (CONTINUED)

GENERAL NOTES

Limitations 2nd Floor

- ❑ No access to the floor from underside
 - Entrance lobby & leasing office with high end finishes
 - Disruption in leasing operations
 - Disruption to tenants of the building
 - Kitchen of the Daily Grill in the area of slab replacement
 - Extensive slab cracking/shoring issues prevent partial slab replacement options



Fire Proofing



M&E Utilities Attached to 3rd Floor



Lobby/Leasing Area



Fiber Reinforcement

Advantages


- No Shoring required
- Minimal surface prep. required
- Minimizes the possibility of leakage
- Easy/Quick
- Should stiffen the slab considerably
- Reduce the possibility of future surface cracking

Limitations


- Not as durable as a new slab
- May only provide temporary fix (depending on the condition of exist. concrete)
- Design is not fire rated (would need to replace FRP after fire event)



Slab with CFRP Strengthening Only



Strengthening with CFRP Fabric+ CFRP Bars




Rehabilitation Approach

- ❑ Repair the cracks and spalls on the floor slab
- ❑ Reinforce a small portion of the slab with CFRP
 - Option 1: CFRP Sheets at the top
 - Option 2: CFRP Sheets at the top + CFRP rods embedded in the slab
- ❑ Monitor the slab for a few months to evaluate the performance of the two repair methods
- ❑ Select repair method for the whole slab



Repair Areas



Crack Repair

- Rout & fill cracks
> 1/32"



Gravity Fill Cracks with Epoxy

- ❑ Sikadur 22
- ❑ Sikadur 52



Routed and Repaired Cracks on the Floor



Flood Coat of Cracks

- Sikadur 52
Fill Cracks < 1/32"



Full Depth Repairs



Carbon Fiber Rod Installation



10/04/2012

Carbon Fiber Reinforced Polymer (CFRP) Installation



Broadcast Topping for Traction



10/10/2012




Structural Monitoring



Instrumentation Layout


- Panel 1: CFRP only
- Panel 2: CFRP + CFRP rods
- Panel 3: Reference (unrepaired)

- Joists 1 to 9:
Strain Gage and Accelerometer at midspan
- Joist 9:
LVDT at Midspan




SENSOR PLACEMENT ON JOISTS

Strain Gages and Accelerometers



Comparison of Accelerometer with LVDT




Loading Vehicle

- 2007 Saturn Vue Greenline FWD Hybrid SUV
- Weight: 3500lbs
- Weight distribution (% front / rear): 59/41
- Wheel base: 106.6in / 2707mm





Deflections over Time - Panel 1


Middle Joist Deflections



Deflections over Time - Panel 2



How is Load Sharing Calculated



$$\text{Load sharing Joist 1} = \frac{D_1}{D_2} \%$$

$$\text{Load sharing Joist 3} = \frac{D_3}{D_2} \%$$



nees@UCLA

The George E. Brown, Jr. Network for Earthquake Engineering Simulation



Base Condition Results - Panel 1 (Unrepaired)





Table of Load Sharing Results

	Tests used		From Deflection Panel 1		From Strain Panel 1		From Deflection Panel 2		From Strain Panel 2	
			Joist 1	Joist 3	Joist 1	Joist 3	Joist 4	Joist 6	Joist 4	Joist 6
Test 04	3-7	Baseline	50%	49%	37%	28%	45%	47%	48%	35%
Test 06	4-7	Routing	39%	54%	36%	35%	42%	49%	46%	34%
Test 11	4 6-8	Repaired	63%	63%	60%	47%	53%	61%	55%	48%
Test 15	2 4 6 8	Week 2	64%	59%	60%	50%	51%	53%	55%	47%
Test 17	3 5 7 9	Month 2	62%	59%	47%	43%	50%	59%	50%	50%
Test 19	1 2 4-8	Month 3	61%	62%	46%	44%	52%	58%	52%	46%




Comparison of Results


Load Sharing - Panel 1
From Strain




Load Sharing - Panel 2
From Strain



Load Sharing - Panel 1
From Deflections



Load Sharing - Panel 2
From Deflections



Interpretation of Results

- ❑ Deflections Reduced by almost 40% (2.5 mm – 1.4 mm)
- ❑ Improved Load Sharing between Joists
- ❑ The behavior appears to have stabilized after the first month



nees@UCLA

The George E. Brown, Jr. Network for Earthquake Engineering Simulation



Results/Recommendations

- ❑ Evaluated Two options
 - CFRP Sheets
 - CFRP Sheets +CFRP Rods
- ❑ Both options have similar behavior
- ❑ Recommended using CFRP Sheets only for the rest of the floor



Phase II Repairs



FRP Application



Adhesion/Bond Testing



Finished Repairs



06/20/2013

Questions!

