

Thomas L. Rewerts, SE  
THOS. REWERTS & CO., LLC  
Kansas City, MO  
[t.rewerts@rewerts.com](mailto:t.rewerts@rewerts.com)

**Complex and Innovative Structural Repair  
of Severely Damaged, 1917 era School Structures**



A comprehensive renovation of two existing, 1917-era concrete-framed, historic school buildings in a Midwestern city resulted in serious structural problems.



The structural problems were severe enough to require evacuation and complete closure of one of the buildings, and portions of the other, until comprehensive structural repairs could be made.







Existing long span, one-way, concrete pan joist floor systems were severely overloaded, and cracked extensively as a result.






SHADED ROOMS ARE WHERE CONCRETE FILL WAS ADDED TO THE EXISTING FLOOR SLAB AND JOIST SYSTEM IN THE 2003-2004 RENOVATION PROGRAM.



**Second Floor Structural Framing Plan**  
Not To Scale

SHADED ROOMS ARE WHERE CONCRETE FILL WAS ADDED TO THE EXISTING FLOOR SLAB AND JOIST SYSTEM IN THE 2003-2004 RENOVATION PROGRAM




Third Floor Plan  
Not To Scale





**NOTES:**

$f'c = 2,100$  PSI - 2ND FLOOR  
 $f'c = 2,500$  PSI - 3RD FLOOR  
STEEL = ASTM A15-14,  
"STRUCTURAL GRADE"  
( $F_y = 33,000$  psi)



Ⓢ Vertical Section Thru Typical Floor Joist Slab System  
Not To Scale


















Room 211  
10-01-09  
TLR



Room 209

10-1-09

TR


















Underside of  
the concrete  
slab above

Face of the  
concrete  
distribution  
beam



Face of the  
joist stem






L0207

L0407

L0507

AUG 6 2010





Underside of  
the concrete  
slab above

Face of the  
joist stem

Face of the  
concrete  
distribution  
beam

NOV 6 2009





























See next Figure















SHADED ROOMS ARE WHERE CONCRETE FILL WAS ADDED TO THE EXISTING FLOOR SLAB AND JOIST SYSTEM IN THE 2003-2004 RENOVATION PROGRAM



**Second Floor Structural Framing Plan**

Not To Scale










HELIX

STAINLESS STEEL RULER FLEXIBLE






SECTION THRU THRESHOLD BETWEEN CORRIDOR & CLASS ROOMS















Load bearing,  
structural clay tile  
interior corridor wall

*Typical interior joist  
framing into window lintel*

Concrete lintel over  
windows, with  
masonry above


Load bearing, brick  
masonry and structural  
clay tile exterior wall






**Cross Section Thru The Typical Concrete Floor Slab & Joist System Illustration Simple Span Behavior**






Cross Section Thru Concrete Floor Slab & Joist System Illustrating the Actual Behavior in This Building (At Window Locations)









*Typical interior joist framing into exterior wall*


Concrete lintel over windows, with masonry above

Load bearing, structural clay tile interior corridor wall

Load bearing, brick masonry and structural clay tile exterior wall


206







Cross Section Thru Concrete Floor Slab & Joist System Illustrating the Actual Behavior in This Building (Away From Window Locations)


















Transverse Cross Section Thru a Typical Concrete Floor Slab and Joist System as Actually Performing























8/27/2010 10:44 PM  
 1  
 2  
 3  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14

1  
 2 6  
 Second Floor - North Work Area  
 1/4" = 1'-0"

2  
 4 6  
 Second Floor - North Work Area - Struct Plan  
 1/4" = 1'-0"

These drawings and all information contained thereon are copyrighted by Thos. Rowe & Co., LLC. No portion of these drawings is to be re-used in any form without the express advance written authorization of Thos. Rowe & Co., LLC. Main St., Suite 215, Kansas City, MO 64111-7711.

THOS. ROWE & CO., LLC  
 Structural Engineering  
 4992 Main St., Suite 215  
 Kansas City, MO 64111-7711  
 816.597.9888 (ext.)  
 816.424.5192 Mobile

**Structural Repairs**  
 Phase II: Concrete Floor System Repairs  
 Allison Traditional Magnet Middle School  
 221 S. Street - White, Kansas

not for construction

North Work Area Plans -  
 Second Floor

REV	002/2010
DATE	Phase II Structural Repairs
BY	For Use Only
ISSUED FOR	TRC10-00B









The initial portion of the repair program provided load relief to the severely distressed slab systems through careful removal of the concrete topping that had been added in the renovation program.





That was followed extensive structural epoxy injection of cracks throughout the floor slab and joists.













11010

02016

02016

02016

11010

02016

02016

11010

11010

11010

















The structural repairs included use of carbon fiber reinforcing to provide additional shear strength to the ends of the historic concrete floor joists.
















The most important aspect of the repair of the floor slab systems included use of external post-tensioned reinforcement to strengthen the ends of the floor joists in the negative moment regions.





1  
6 11 Side Elevation- Concrete Joist Strengthening Detail  
1 1/2" = 1'-0"







Partial Side Elevation of Concrete Joist- Showing New Channel Anchorage for Strengthening Rods

1 1/2" = 1'-0"















Vertical Section Showing Bolted Connector Detail for Channel Anchorage Assembly



3" = 1'-0"















**Vertical Section thru Distribution Beam at 2nd Floor Level**

1 1/2" = 1'-0"

JOIST



















$$\begin{array}{r} 25' 11" \\ - 17' 3" \\ \hline 8' 5" \end{array}$$
 25' 11" 2/10  
 17' 3" 3/10  
 8' 5" 2/10

25' 11" 2/10  
 17' 3" 3/10  
 8' 5" 2/10



OCT 29 2009















The repairs included installation of mechanical shear connections between the damaged concrete floor systems and the internal and external shear walls, to restore the horizontal shear transfer capacity.






Vertical Section- Lateral Support and Shear Transfer Detail- Exterior Wall-to-Floor Interface

1 1/2" = 1'-0"








B  
13 13

Plan  
1 1/2" = 1'-0"













CORROSIVE

BULL  
Series

Eggers













Selected areas of the existing concrete floor slab were in such bad condition, steel plates had to be installed to bridge between the joists below to prevent punching shear failures through the slab.













35ft  
ft  
in  
1  
2  
3  
4  
STANLEY®  
Sward®









Finally, a new, lightweight, raised ceramic and metal flooring system was installed on the concrete floor slab systems to replace the concrete fill that had overloaded those floor systems during the renovation.




**NOTE:** REFER TO RAISED FLOOR INSTALLATION PROCEDURE ON THIS SHEET.

NEW LIGHTWEIGHT COMPOSITE STEEL RAISED FLOORING SYSTEM; 24" SQUARE PANELS (SEE SPECIFICATION SECTION )


**NOTE:** REFER TO FIGS. 25-1 AND 25-2 FOR EXAMPLES OF THE ROUGHNESS OF THE EXISTING TOP OF SLAB SURFACE.

PERIMETER MASONRY WALL

**NOTE:** THIS NEW RAISED FLOOR SYSTEM TO BE INSTALLED IN ROOMS 205, 206, 208, 209, 211, 215, 302, 303, 304, 305, 306, 307 AND 315.



**NOTE:** REFER TO




FOR ILLUSTRATIONS OF HOW THE FLOOR SLAB SYSTEMS ARE DEFLECTED IN THIS STRUCTURE

C  
18 | 18

Vertical Section Thru New Lightweight Raised Floor System

1 1/2" = 1'-0"





























Installation of large banks of new HVAC ducts through interior load-bearing structural clay tile walls caused serious vertical displacement and near collapse of a section of the concrete floor system in one area of one of the buildings.






























The partially collapsed floor system was raised back into its original orientation with a system of hydraulic jacks, and a new concrete masonry wall constructed to replace the severely damaged structural clay tile wall that originally supported the displaced floor slab section.























































EXIT

Office →  
Cafeteria →

110

Walking

"Failure is not an option"

CA

CDSGP

- C - caught
- D - doing
- S - something
- G - good
- P - program

When a student is consistently doing the right thing and / or goes above and beyond in being good and respectful.

Thank you!



Thomas L. Rewerts, SE  
THOS. REWERTS & CO., LLC  
Kansas City, MO  
[t.rewerts@rewerts.com](mailto:t.rewerts@rewerts.com)

**Complex and Innovative Structural Repair  
of Severely Damaged, 1917 era School Structures**