

INTERNATIONAL GONGRETE REPAIR INSTITUTE ICRI 2015 Spring Convention March 25-27, New York, NY High Rise Repairs



Impressed Current Cathodic Protection as a Means of Preventative Masonry Conservation: 20 Year Retrospective

Gina Crevello, Echem Consultants LLC Paul Noyce, Axieom LLC

### Content

- Steel Frame Evolution
- Early Signs
- Corrosion Basics
- Traditional Repairs
- Cathodic Protection
- Case Studies
- Rationale
- Summary


### Monadock Building (1891) Burnham & Root

- Skyscraper Proto-type
- Tallest load bearing masonry structure in the world
- Base of Structure (6ft)




#### Home Insurance Building (1884 demolished) William Le Baron Jenney

- Transition from Load Bearing walls to Skeleton Frames
- Three types of metal in early construction, steel preferred as technology advanced
- Early construction details have masonry tightly wrapped around frame




#### Rand McNally Building (1890, demolished) steel frame Burnham & Root


- Burnham and Root, Chicago Architects perfected steel frame construction
- Root Developed Foundations to spread load
- Masonry Cladding became obsolete after WWII



#### Masonic Temple, 1892

Demolished, x-braced Burnham and Root





Chicago, showing Wind-bracing.



#### Reliance Building, 1895 Burnham and Atwood



Empire State Building, 1930 Shreve, Lamb and Harmon

Early Signs

## Early Signs


#### Issues in the UK labelled

Regent Street Disease

Deansgate Disorder

Damages to the façade found to be Primarily Corrosion

UK Department of the Environment and Historic Scotland Investigations led to the publication of TAN 20.



# Early Signs

#### <u>Issues in the US labelled</u>

Corrosion noted in early 1900s

Façade Failures in NYC lead to Local Law 10 now 11 Grace Gold Memorial

#### Killed from falling masonry

#### Grace Gold's Legacy: Safer Buildings

Posted on March 24, 2015 by Stephen A. Varone, AIA

Those of us in the engineering and architecture industry in New York City are fully familiar with the Facade Inspection and Safety Program (FISP), formerly known as Local Law 11/98 and in its original form, Local Law 10/80. But while many buildings industry professionals know about the facade inspection law, fewer know about the person whose tragic death was behind it.

That person was Grace Gold, a 17-year-old freshman student at Barnard College who was killed in 1979 when a loose piece of masonry fell from a building on Broadway and 115<sup>th</sup> Street. Grace's death led to the original



Grace Gold's death from a falling piece of masonry in 1979 led to New York City's facade inspection law.

facade inspection law, New York City's Local Law 10 of 1980, which required buildings taller than six stories to have their street-facing facades inspected for unsafe conditions every five years by a qualified engineer or architect.

## Liability Issues (UK)

#### Liability High when NO Corrosion Knowledge



#### Surveyor negligence claims for Regents Street Disease

If you have received a survey report from a professional surveyor which has failed to take into account structural damage such as that caused by Regent Street Disease, it may be possible to make a negligence claim against the surveyor responsible.

#### What is Regent Street Disease (RSD)?

Although it has a very place-specific name, Regent Street Disease (RSD) is not confined to London's Regent Street. In fact, it is known by various other names. For example, in Manchester the problem is referred to as Deansgate disorder.

Whatever its name, the "disease" is confined to buildings, usually from the early 20th century, which have been built using a steel frame then covered in facing stone, brick, faience or terracotta.

Problems arise when moisture permeates the stonework façade and begins to rot the internal steelwork, eventually causing the frame to corrode and potentially give way.

#### Warning of 'time bomb disease' that threatens to destroy city buildings

By The Bristol Post | Posted: October 31, 2012

#### Comments (0)

SCORES of buildings in Bristol are being attacked from within by a condition known as Regent's Street Disease – according to a leading property expert.


Steel framed properties which were built around a century ago are in danger of literally crumbling and falling apart.

# **Corrosion Basics**

#### **Corrosion Basics**


Thickness of Rust (mm)


5




Age of Building (Years)

**The Corrosion Timeline: Three Phases** 






#### **Corrosion Basics**



Loss of Section


### Corrosion Basics – Cracking Effects



### Corrosion Basics – Cracking Effects




## Corrosion Basics – Cracking Effects



### Corrosion Basics – Displacement




#### Corrosion Basics – Displacement



### **Corrosion Basics – Spalling**





### Corrosion Basics – Spalling






### **Corrosion Basics – Spalling**



### Corrosion Basics – Severe Corrosion




### Corrosion Basics – Catastrophic Failures







**Current Practices** 















# **Cathodic Protection**

The Black Magic

### Cathodic Protection

1824

1928

1930s


1959

- Ships
- Pipelines
- Tanks
- Concrete
- Concrete
- Concrete
- FHWA Approval 1973 SHARP Report 1983
- GCP on Concrete in Marine or Contaminated Environments


GCP GCP or ICCP GCP or ICCP ICCP ICCP ICCP







Monitoring System



Early investigative work in the UK was Conservation Driven not Health & Safety or Cost Driven



DOULTON

AND CO., LTD.





- ICCP Historic buildings First Trials (UK – English Heritage) First full Scale Application UK US 2004
- First Large Scale Use



1990

1996

Colonnade, Prime Minster's Residence, Dublin, Ireland 1990 Installation 2012 system still performing

ICCP

#### Historic buildings




**Inigo Jones Gateway** Arch, Chiswick House Gardens, London, UK 1995 Installation - 2014 system still performing

First Full Scale Use on an Historic Steel Frame Buildings UK




**Joshua Hoyle Building** Manchester, UK 1996 Installation - 2013 System still performing

First Full Scale Use on an Historic Building USA




Marshall Field's Flagship Store Chicago, IL 2004 Installation 2013 System still performing


- Early Anode Use for ICCP
- Ribbon Anodes installed in joints
- Probe anodes used for better current distribution





What happens when anodes are too close to the surface?








# **Case Studies**

#### Case Study – Marshall Field's

- Ist Use of ICCP on Heritage Building in US (2004)
  - 1920s steel frame construction, addition to earlier structure
  - Third Repair Cycle
  - Water infiltration over many years lead to corrosion of the embedded steel
  - ICCP Trial was successful
  - Design of system at upper terra cotta clad pilasters








#### Case Study – Marshall Field's

- Four Zones
- Early ballasted rod anode with graphite paste
- Interconnected with Ti Wire
- Ag/AgCl Reference Electrodes installed for monitoring
- Touch Screen computer for ease of monitoring/ dial in
- Operating Currents at most recent monitoring trip
  - Z1 3V
  - **Z2** 6.26V
  - Z3 6.74V
  - Z4 4.16V
- 34mA 270 mA 200mA

25mA

(7% Operating Current) (8% Operating Current) (47% Operating Current) (29% Operating Current)







## Calhoun College


- 1931 Construction, extremely detailed collegiate gothic campus building
- Long Term Owner
- 50 year design life of restoration repairs.
- Corrosion deterioration cracking valuable masonryMasonry replacement is very costly





#### Case Study – Calhoun College

- Largest ICCP system in US on heritage building to date
  - 35 Zones, 140 AgAgCl Reference Electrodes
  - Over 6,000 LF of steel protected and 4161 anodes used
  - Better designed ballasted anodes allowed for larger anode zones with greater amounts of steel afforded protection
  - No concerns about acidification or current dump





#### Case Study – Calhoun College

#### Anode Performance

- Current density on anode surface 57.3mA/m<sup>2</sup> which is half of operating current density
- Average Current density is 43.3 mA/m<sup>2</sup>
- All zones met the 100mV criteria at 30 days and at 3  $\frac{1}{2}$  years.
- Average current density per anode has dropped to 24.8



Anode Performance	Output per Anode (mA) 30 Days	Output (mA) 3 ½ Years
Мах	0.405	0.405
Min		0.006
Average		0.175
Standard Deviation	0.117	0.121



# Preservation38 Carraraware units removed in total






# CostDeconstruction not feasible





- Long term durability of repair
- Desire for fewer repair cycles





- Many of these buildings have landmark status
- Some cladding material cannot be replaced in kind
- Traditional repairs are costly, unsightly and/or a shorter term solution
- Stewardship for future generations





### Summary


#### Summary


- While most buildings of steel frame vintage will have experienced some deterioration, where masonry has not yet been damaged its use can be highly valuable
- ICCP used with traditional repairs provides at 50+ repair life.
- Minimizes future repair cycles
- Corrosion related deterioration can be predicted and known maintenance costs can be better projected
- Technology is constantly evolving,
- Systems can now run on battery operated super capacitors systems, solar panels, piso electric, etc.

### Summary

- Summary Not a new technology
- 1824 First discovered use of CP
- 1990 First trial/ Same time as Sony PlayStation was brought to market
- 1994 First full scale building UK / Same time as HDTVs were developed
- 2004 First larae scale application in US







#### **Corrosion Condition Assessments**

## Thank you.. Questions?

#### Gina Crevello

- Principal
- Echem Consultants LLC
- gcrevello@e2chem.com
- **8**45-215-4370
- 201-705-9050

#### Paul Noyce

Principal

Axieom LLC

#### pnoyce@axieom.com

845-215-4363 201-565-6461