

April 5, 2022
ICRI 2022 Spring Convention

Case Study – Precast Concrete Louver Repairs



Christopher Kottra
Principal
Building Technology Consultants, Inc.



The ideas expressed in this ICRI hosted webinar are those of the speakers and do not necessarily reflect the views and opinions of ICRI, its Board, committees, or sponsors.

Learning Objectives

- Understand importance of identifying sources of deterioration before implementing repairs
- Understand value of developing multiple repair options for building owners so they can make educated decisions on the maintenance of their building.
- Derive logistical challenges during construction and the value of a collaborative team effort.
- Realize value of planning for large projects proactively vs. reactively.

Overview

- 61-story condo building
- Built in 1990
- 15-story parking structure abuts tower
- Facade:
 - Precast panels with exposed aggregate finish
 - Precast concrete louvers at 1st through 15th floors







800 CLOREOUT-317-245-3711

Overview

- Concrete louver configuration:
 - 6 trapezoid-shaped horizontal rungs
 - Lower floors – Solid panels with replicated rungs
 - Total of 492 louvers







History

- Concrete deterioration identified in 2008




8NAB



History

- Concrete deterioration identified in 2008
- Partial or full-depth repairs performed in 2009





150


History

- Concrete deterioration identified in 2008
- Partial or full-depth repairs performed in 2009
- Adjacent areas exhibited deterioration within a few years
- Deterioration progressed faster than anticipated

Ring Anode Effect (Halo Effect)


- Accelerated corrosion of reinforcing around patches
- Occurs when patch properties are different than surrounding concrete
 - Conductivity
 - pH
 - Permeability (moisture)

Figure A



*Image from concreteprotection.com


Figure B



*Image from concreteprotection.com

Figure C

PATCH




*Image from concreteprotection.com



History


- Deterioration attributed to:
 - Insufficient cover over reinforcing steel
 - Near horizontal surfaces on louver rungs
 - Salt spray from Lake Shore Drive






Development of Repair Options


- Conceptual repair options developed in 2015
 - Level 1:
 - Conventional concrete repairs
 - Acrylic waterproofing coating
 - Level 2:
 - Conventional concrete repairs
 - Elastomeric waterproofing membrane




1 TYPICAL ELEVATION AT TYPE I LOUVER REPAIR
1/2" = 1'-0"




2 TYPICAL SECTION
1/2" = 1'-0"




3 REPAIR SECTION
3" = 1'-0"




4 REPAIR SECTION
3" = 1'-0"



6 TYPICAL ELEVATION AT TYPE II LOUVER REPAIR
 $1/2'' = 1'-0''$



7 TYPICAL SECTION
 $1/2'' = 1'-0''$




8 REPAIR SECTION
3" = 1'-0"

Development of Repair Options

- Conceptual repair options developed in 2015
 - Level 1:
 - Conventional concrete repairs
 - Acrylic waterproofing coating
 - Level 2:
 - Conventional concrete repairs
 - Elastomeric waterproofing membrane
 - Level 3:
 - Over-cladding with prefabricated GFRC “caps”
 - Level 4:
 - Remove rungs
 - Install prefabricated aluminum louvers

NEATLY REMOVE CONCRETE LOUVER RUNGS INCLUDING REINFORCING STEEL, TYP.

REMOVE EXIST. METAL BLANK-OFF CHANNELS FROM INTERIOR FACE OF LOUVERS (NOT SHOWN FOR CLARITY)




STEP 1
EXTERIOR VIEW

CUT EXIST. REINFORCING STEEL FLUSH WITH FRAME AND COAT EXPOSED ENDS WITH CORROSION-INHIBITING COATING


PROVIDE ACRYLIC COATING OVER FRAME WHERE CONCRETE LOUVER RUNGS ARE REMOVED

PERFORM CONCRETE PATCH REPAIRS ALONG PERIMETER OF CONCRETE LOUVER FRAMES WHERE DESIGNATED BY ENGINEER.



STEP 2
EXTERIOR VIEW

PREFABRICATED ALUMINUM LOUVERS. SEE SHEET AR-505



STEP 3
EXTERIOR VIEW

Repair Recommendations

- Highest level of repairs for highest chloride exposure
- Lower-level repairs for other areas
- Recommended a combination of Level 1, 2, & 4 repairs











EXIST. CELLULAR EQUIPMENT COORDINATE TEMPORARY SHUT DOWN AND/OR REMOVAL AND REINSTALLATION WITH CELLULAR SERVICE PROVIDER

EXIST. PRECAST CONCRETE FACADE PANELS WITH EXPOSED AGGREGATE FINISH. PERFORM CONCRETE PATCH REPAIRS WHERE DESIGNATED BY ENGINEER. ROU AND SEAL CRACKS WHERE DESIGNATED BY ENGINEER. SEE DETAILS 04R-003 AND 04R-005.

EXIST. PRECAST CONCRETE LOUVERS. PERFORM CONCRETE PATCH REPAIRS AT TYPE I AND TYPE II LOUVER JOINTS DESIGNATED BY ENGINEER. ROU AND SEAL CRACKS IN CONCRETE LOUVERS WHERE DESIGNATED BY ENGINEER. SEE DETAILS 04R-003 THROUGH 04R-005 AND 04R-006.

REPLACE EXIST. CONCRETE LOUVERS IN PREFABRICATED ALUMINUM LOUVERS. SEE SHEET AR-004


PRECAST CONCRETE LOUVER FINISH SCHEDULE	
	PREFABRICATED COATED ALUMINUM LOUVERS (BASE BID)
	SILICONE ELASTOMERIC COATING (BASE BID)
	ACRYLIC PROTECTIVE COATING (BASE BID)

LEGEND	
	TYPE 1 SEALANT JOINT
	TYPE 3 SEALANT JOINT
	TYPE 4 SEALANT JOINT
	TYPE I CONCRETE LOUVER
	TYPE II CONCRETE LOUVER

1 PARTIAL EAST ELEVATION
1/8" = 1'-0"

Repair Implementation

- Shared financial responsibility for facade maintenance
- Extensive deliberation between HOA and commercial owner
- Periodic make-safe repairs until full repairs could be implemented








Meanwhile.....

- Sealant at precast joints and window perimeters neared end of useful life
- HOA budgeted for proactive comprehensive sealant replacement project in 2018 and/or 2019









REMOVE AND REPLACE WINDOW PERIMETER SEALANT AT WINDOWS ON 16TH FLOOR AND ABOVE, TYP.

REMOVE EXPOSED PORTIONS OF EXIST. GLAZING GASKETS WHERE DESIGNATED BY ENGINEER AT WINDOWS ON 16TH FLOOR AND ABOVE. PROVIDE NEW LIQUID-APPLIED GLAZING SEALANT WHERE EXPOSED PORTIONS OF EXIST. GLAZING GASKETS ARE REMOVED

1 ENLARGED PARTIAL ELEVATION
1/4" = 1'-0"

EXIST. PRECAST CONCRETE FACADE PANELS WITH EXPOSED AGGREGATE FINISH. PERFORM CONCRETE PATCH REPAIRS WHERE DESIGNATED BY ENGINEER. ROUT AND SEAL CRACKS WHERE DESIGNATED BY ENGINEER. SEE DETAILS 5/AR-503 AND 9/AR-503.

PROVIDE WINDOW SCREENS ADJACENT TO EXISTING WINDOW SCREENS, TYP. (ALTERNATE 2).

LEGEND	
	TYPE 1 SEALANT JOINT
	TYPE 2 SEALANT JOINT
	TYPE 3 SEALANT JOINT
	TYPE 4 SEALANT JOINT
	EXIST. WINDOW SCREEN
	NEW WINDOW SCREEN

Repair Implementation


- Timelines converged
- The 2 projects became one
- Construction documents prepared in 2018
- Project awarded in January of 2019
- Work began in March of 2019

Repair Implementation

- Logistical challenges early on:
 - Longer lead-time for replacement louvers
 - Access around wall-mounted cellular equipment
- Contractor ran 8 swingstages
- Flexibility in daily work







Repair Implementation

- Louver replacement
 - Metal channel replacement (win-win)








STEP 4
EXTERIOR VIEW

REINSTALL EXIST BLANK-OFF
CHANNEL ASSEMBLIES.
RELOCATE EXIST Z-GIRTS AS
NECESSARY TO ACCOMMODATE
NEW LOUVERS

PREFABRICATED ALUMINUM
LOUVERS. SEE SHEET AR-505



STEP 5
INTERIOR VIEW



Repair Implementation

- Louver replacement
 - Metal channel replacement (win-win)
 - Staged workers inside garage for efficiency



211
Residential
Background Check







Repair Implementation

- Other miscellaneous repairs
 - Concrete patch repairs
(matching the exposed aggregate finish)
 - Glazing gasket replacement
 - Failed IGU replacement
 - Window screen replacement
 - Expansion joint between garage & adjacent building

Project Stats

- Original Contract: \$3.3M
- Final Construction Cost: \$2.8M
- Completed in ~10 months (December 2019)
- 57 precast louvers replaced with aluminum
- 46 precast louvers received elastomeric coating
- Remaining 389 louvers received acrylic coating
- ~60,000 linear feet of sealant replacement (>11 miles)















Summary

- Evaluation process identified sources for deterioration
- Advanced planning allowed for...
 - Development of repair options
 - Association to build funds
 - Proactive facade repairs (sealant)
 - Collaborative effort among project team
 - Under budget



WARNING

SKY CLEANER





Questions?

Christopher Kottra, PE (IL), REWC, CCCA
Building Technology Consultants, Inc.
1845 East Rand Road, Suite L-100
Arlington Heights, Illinois 60004

Direct: (847) 454-8818

E-mail: ckottra@btc.expert

Website: www.btc.expert



INTERNATIONAL CONCRETE REPAIR INSTITUTE
1000 WESTGATE DRIVE, SUITE 252
ST. PAUL, MINNESOTA 55114 USA
P: +1 651-366-6095 | E: INFO@ICRI.ORG | WWW.ICRI.ORG