HYBRID COATINGS, CONCRETE **RESTORATION & SEISMIC SURPRISES:** A CALIFORNIA CASE STUDY

James E. Mendygral, PE **Associate Principal** Simpson Gumpertz & Heger, Inc.

12 April 2018



Jim Mendygral, PE **Associate Principal** Simpson Gumpertz & Heger, Inc. San Francisco, CA



and Building Enclosures

- BS Civil Engineering
- MS Architectural Engineering
- 17+ years experience
- Building enclosure and structural engineering






Project Basics


- Outdoor mall and movie theater complex
- Issues with exterior service corridor since day one
- Owner in need of reliable long-term fix

Project Site




Service Corridor





PARTIAL NORTH/SOUTH SECTION - LOOKING WEST





Service Corridor Section "The Catwalk"












Cracks, Spalls, and Unadhered Coatings





Distress at Deck Drains











Failed Expansion Joint





Catwalk Soffit



Many questions...

- Why so much cracking and spalling?
- What materials were used?
- Why did they fail?
- Palletized hand trucks?





As-Built Coating Terminations



As-Built Coating Terminations















Specified


As-Built









Petrographic Analysis











But wait...



This deck was stacked...




- Failed coating
- Broken drains
- Unbonded overlay
- Flat structural deck
- Heavy palletized hand jacks
- "Catwalk" must remain open...






Repair Strategy




- Restore concrete deck
- Eliminate sloping compound
- Reliable waterproofing
- Build-up "bird baths" where feasible
- Tough wear resistance









Typical Details





Seismic Joint Details










Construction Phase

- Phasing plans
- Demolition off-hours
- Close coordination with users
- Mockups










Mock-Ups

- Surface prep ICRI CSP 3-4
- **Primers**
- Peel strength testing (ASTM D903)
- Benchmark application quality













Guess again...






More trouble at the Drains...

- RFI
- No. 6 bars cut at drains
- Does it matter?
- Work stops...






21 of 24 Drains **Impacted**














"Chord Forces"



Seismic Solutions?

- LATERIA ACTIO AND SPINCE I COST INVITER CASIDICI
- remoninaliary 313 to determine
- Carbon Fiber Reinforced Polymer (CFRP) Reinforcement







CFRP Reinforcing Rods

- Near surface application
- Compatible with specified coating repairs
- Readily available
- Familiar to restoration subcontractor already on the job



















Back on track...
































Project Completed 2016









2018 Update...















Thank You

jemendygral@sgh.com

