DETERIORATION, DEFECTS AND REPAIR OF ABOVE THE GROUND SWIMMING POOLS AND SUPPORTED DECKS

Dunja Vla, Predrag Popovic Wiss, Janney, Elstner Associates, Inc., Northbrook, IL, USA









WHAT IS UNIQUE ABOUT THE ABOVE GROUND POOL STRUCTURES?

- Constantly exposed to harsh environment
 - Chemically treated water
 - High humidity
- Space below them is occupied
 - Used for storage
 - Parking
 - Office space
- When they leak it affects the space below them

TYPES OF POOL FINISHES

- Ceramic tiles
- PVC liners
- Plaster
- Stainless steel

TYPES OF DECK FINISHES

- Ceramic tiles
- Concrete
- Membrane
- Precast concrete pavers





TYPES OF STRUCTURAL FRAMING

- Conventionally reinforced concrete slabs and walls
- Pre / post tensioned concrete slabs and walls
- Concrete composite metal slabs with conventionally reinforced concrete walls supported by steel structural framing

TYPES OF DECK DRAINAGE

- Linear drains along the deck
- Linear drains incorporated into the pool gutter
- Drain heads located below deck precast concrete pavers on pedestals







INDOOR POOLS AT RECREATIONAL FACILITIES, SCHOOLS AND UNIVERSITIES

- **Competition pools**
- **Leisure pools**
- **Kiddie pools**







INDOOR POOLS AT HIGHRISES / CONDOMINIUM ASSOCIATIONS/ APARTMENT BUILDINGS









OUTDOOR POOLS AT ATAPARTMENT COMPLEXES AND MUNICIPAL RECREATIONAL FACILITIES











TYPICAL DISTRESS

- Cracked and debonded tiles
- Cracked and deponded plaster
- Leakage
- Concrete delaminations /spalls
- Corrosion of metals
- Clogged drains / leaking drains
- Sealant debonding / deteriorating / staining
- Damaged grates
- Bulkheads deteriorated bearings
- Deteriorated retractable bleachers
- Corroded / broken wires supporting ducts at the ceiling of indoor pools





CRACKED AND DEBONDED TILES












LEAKAGE









CONCRETE DELAMINATION









DIVING PLATFORMS

- **Concrete deterioration at platform edges**
- **Corrosion of metal**
- Peeling off rubber mats















DRAINS









REPAIR OF THE OLYMPIC SIZE POOL


- Pool and deck lined with ceramic tiles
- Three diving towers
- Two bulkheads
- Bleachers
- Underwater windows








PLAN VIEW









POOL DECK CROSS SECTIONS








EXISTING SECTION THRU EAST POOL DECK





LONGITUDINAL CROSS SECTION THROUGH THE POOL








INVESTIAGATION

TOP OF THE DECK SLAB DELAMINATION

SURVEY





























UNDERSIDE OF THE DECK SLAB DELAMINATION AND WALLS SURVEY


















DELAMIANTION AT UNDERWATER WINDOWS








DELAMINATION SURVEY OF THE POOL WALLS AND BOTTOM




















BULKHEADS – WORN OUT BEARINGS AND CORROSION












REPAIRS







REPAIRS OF THE TOP OF THE DECK















• REPAIRS OF THE UNDERSIDE OF THE DECK









CASTING OF CONCRETE TOPPING OVER WATERPROOFED SLAB








INSTALLTION OF TILES















REPAIRS INSIDE THE POOL











CLEANING OF BULKHEADS







REPAIR OF THE POOL AT SENIOR INDEPENDENT LIVING HIGHRISE

- **Pool lined with plaster**
- **Deck lined with ceramic tiles**








PLAN VIEW

EXTENT OF JOINT SEAL -P00L (C DASHED LINE INDICATES EXTENT OF WORK. EXTENT OF JOINT SEAL REPLACEMENT, LAP WITH GREENHOUSE E POOL - PARTIAL THIRD FLOOR PLAN


CROSS SECTION THROUGH THE POOL








CROSS SECTIONS THROUGH THE POOL WALLS AND SLAB





SECTION THRU SWIMMING POOL * SCALE: 1/4" = 1'-0" (LOOKING NORTHWEST)





INVESTIGATION





- INSIDE THE POOL
- POOL DECK





• UNDERSIDE OF THE POOL
















REPAIRS








TOP OF THE DECK AND INSIDE THE POOL








UNDERSIDE OF THE POOL














RETROFIT OF A GUTTER




Repair detail - installation of gutter skirt







INSTALLATION OF SETTING BED, WATERPROOFING MEMEBRANE AND DECK TILES









• INSTALLATION OF WATERPROOFING MEMEBRANE INSIDE THE POOL





INSTALLATION OF PVC LINER















RESTORED POOL









REPAIRS OF DIVING TOWER















