

RESTORATION SERVICES

- Condition Assessment
- Façade/Building Envelope
 Survey
- Plaza Leaking/Waterproofing Review
- Forensic Investigation
- Structural Analysis
- Repair/Rehabilitation
- Leak Mitigation

PARKING SOLUTIONS

- Structural Engineering
- Functional Design
- Architecture
- Prime Design
- Design-Build Criteria









JOHNS ISLAND CLUB PARKING DECK PLAZA REHABILITATION



Andrew Kong Restoration Manager



ENGINEERING // TRANSPORTATION // STRUCTURES // ENVIRONMENTAL // SURVEY // SUE // LANDSCAPE ARCHITECTURE // PLANNING // WATER RESOURCES // CREATIVE SERVICES // PARKING SOLUTIONS

About me	
Experience	15+ years of parking, plaza systems & building enclosure related experience
Education	MBA (Duke University – Fuqua School of Business) & M.Sc. (Queens Univ. – Ont., Canada)
Expertise	Restoration Engineering – Program Management – Operations – Process Improvement




AGENDA

- ✓ Basic plaza design & types
- ✓ Investigation and prior repairs
- ✓ Client expectations
- ✓ Challenges
- ✓ Implementation
- ✓ Outcome
- ✓ Lessons learned






BASIC PLAZA DESIGN





BASIC PLAZA DESIGN





PLAZA SYSTEMS - PUBLIC THOROUGHFARE









PLAZA SYSTEMS - GREEN ROOF & COURTYARD







INVESTIGATIONS & PRIOR REPAIRS

- Most problems start below the surface.
- Excavations need to be thorough
 - Go to the structural slab
 - Identify key locations
 - Drains
 - **Expansion Joints**
 - **Terminations**
 - **Transitions**
 - Obtain samples
- Things to look for
 - Material failure
 - Design/detailing issues
 - Drainage issues
 - Construction deficiencies








CLIENT EXPECTATIONS

- Aesthetics
- Schedule
 - Pre-planned events
 - Utilization of the club house by members
- Oversized ambulance access
- Budget constraints
- Long-term results





THE PLAZA LAYOUT






CHALLENGES

- Lower level occupied
- Existing details
 - **Expansion joints**
 - Trench drains
- Existing elevations
- Conduit in planter boxes
- Planter drains
- Planter detailing













IMPLEMENTATION

- Hot-Applied Rubberized Asphalt
- Long track record of successful performance
- Bonded to substrate
- Fabric reinforced
- Verify compatibility with substrate, previous membrane, form release agents.
- Sensitive to moisture in concrete.
- Fumes/noise from kettle.
- 215 mils typical with 10-year warranty






6 BY-LEVEL PLAZA DRAIN DETAIL

REFER TO PLANS


& SPECS FOR SIZE

- TOPPING SLAB



NOTE: REFER TO SPECS FOR FIX SET MORTAR BED REQUIREMENTS.

NEW PLAZA WATERPROOFING SYSTEM



7 NEW BY-LEVEL TRENCH DRAIN DETAIL



TWO LEVEL DRAIN COMPLETE W/

DOUBLE DRAINAGE FLANGE, WEEP

& ADJUSTABLE COLLAR

HOLES, BOTTOM OUTLET, ROUND TO

IMPLEMENTATION - CONT.

- Surface preparation
- Phasing
- Testing of different mortar mixes
- Mock up of waterproofing
- New detailing











IMPLEMENTATION - CONT.

- Detailing of unforeseen conditions
- Weather condition











IMPLEMENTATION - CONT.















OUTCOME







OUTCOME - CONT.





LESSONS LEARNED

- Sequencing
 - Planter box mortar will leak
- Think outside the box detailing
- Know your teams capability and experience
- Ensure scope is clear



ACKNOWLEDGEMENT & QUESTIONS

- Weitz Company
 - Nick Pizza, John Stokely & Steve Provines
- Western Specialty Contractors
 - Porter Croft
- Johns Island Club
 - Rex Wilson, MBA



