




**Restoration and Renovation of the  
CWRU Maltz Performing Arts Center**




Ronald M. Czaplicki, PE  
*Vice President*



Mark D. Heinzen, PE  
*Senior Project Engineer*




2016 Fall Convention | November 9-11 | Cleveland, Ohio


















### Field Mark Color Legend



BLUE	DEBONDED, VIBRATING TILES
RED	PARTIALLY DEBONDED TILES
YELLOW	CRACKED CEILING TILES
ORANGE	CRACKED WALL TILES
GREEN	CRACKED TILES – HAIRLINE WIDTH
TAN	CRACKED MORTAR JOINTS





















**Restoration and Renovation of the  
CWRU Maltz Performing Arts Center**

Ronald M. Czaplicki, PE  
*Vice President*

Mark D. Heinzen, PE  
*Senior Project Engineer*

**Questions?**

INTERNATIONAL CONCRETE REPAIR INSTITUTE  
2016 Fall Convention | November 9-11 | Cleveland, Ohio